


FIG. 1A

Prior Art

FURNACE CURE / POROGEN BURNOUT



WEAK  
INTERFACE

FIG. 1B




FIG. 2A

HOT PLATE BAKE / PARTIAL BURNOUT  
OR SURFACE POROGENS




FIG. 2B

APPLICATION OF ETCH STOP LAYER  
AND TOP POROUS SILK LAYER





FIG. 2C

FURNACE CURE / POROGEN BURNOUT



IMPROVED  
ADHESION

FIG. 2D




FIG. 3




FIG. 4